
1/2" x 2" grade 5 hex tap bolt


Restraint Cable

Use 1/4" x 4' long 7 x 19 strand galvanized cable with 1/2" eyelets and 1/2" bolts. Attach one end to the panel approximately 6" below the girt line(and below endlap, if present) and the other end to the framing member.

Use two cables per panel on panels less than 66 sq. feet. Use 3 cables per panel on panels greater than 66 sq. feet.



D.A. Black Company 2227 Village Lake Drive Charlotte, NC 28212 704-537-1110



1/2" x 4" stainless steel cable bolt with 2-1/2" OD washer

Example Only-Do not use this restraint cable detail for explosion venting job. Contact us so that we can determine the correct layout for your job.

Restraint Cable Detail